



UCHWYT PROSTY

Symbol	A [mm]	B [mm]
U-200	200	100
U-300	300	100
U-400	400	100
U-500	500	100
U-500	600	100
U-700	700	100
U-800	800	100
U-900	900	100
U-1000	1000	100

